


CARGO TRANSFER PROCEDURES


FMT 3062

CARGO PIPING DIAGRAM




CARGO TRANSFER PROCEDURES FMT 3062

STRIPPING PIPING DIAGRAM



CARGO TRANSFER PROCEDURES FMT 3062

155.750 (d) (1) VAPOR COLLECTION SYSTEM LINE DIAGRAMS



- 1 8" VAPOR PRESENTATION VALVE
- 2 8" VENT RISER BLOCK VALVE
- 3 8" VENT RISER W/ RAIN CAP
- 4 1 METER STICK GAUGE
- 5 "HERMETIC" VALVE (FOR CLOSED GAUGING DEVICE)

- 6 HIGH LEVEL ALARM
- 7 SIGHT GLASS / GAUGE TREE
- VI +1.5 / -0.5 HIGH VELOCITY P/V VALVE