

# KIRBY INLAND MARINE

## ANNUAL CARGO PIPING AND HOSE TEST REPORT

Reference: 33CFR 156.170

A copy of this report is to be retained on board the vessel.

Vessel Name:401

DATES TEST PERFORMED : PIPING 30 MAY 2017  
CARGO PRESSURE RELIEF VALVES 30 MAY 2017

AIR RECEIVER 30 MAY 17

PORTABLE HOSE # 1: TESTED 6 FEB 18, MAWP: 125 PSI TEST PSI 200  
4" x 75 WILCOX #1151 GG MARINE MASTER DOCK HOSE SER. # 57199-3

PORTABLE HOSE # 3: TESTED 28 DEC 17, MAWP :125 PSI TEST PSI 200  
6" x 60 WILCOX #1151 GG MARINE MASTER DOCK HOSE SER. # 53976-4


PORTABLE HOSE # 4: TESTED 30 MAR 17, MAWP :125 PSI TEST PSI 200  
6" x 75 WILCOX #1151 GG MARINE MASTER DOCK HOSE SER. # 58690-2(PFO)

PORTABLE HOSE # 5: TESTED 06 APR 17, MAWP: 125 PSI TEST PSI 200  
6" x 75 WILCOX #1151 GG MARINE MASTER DOCK HOSE SER. # 67079

Test performed at: Port of Miami, Florida

Test method: Hydro Test

Signature:



AMOS DELANCY

Title:

MARINE COORDINATOR

Company addr

1020 Port Blvd.  
Miami, Florida 33132  
(305)579-5013

Telephone: