

KIRBY INLAND MARINE

ANNUAL CARGO PIPING AND HOSE TEST REPORT SUMMERY

Reference: 33CFR 156.170

A copy of this report is to be retained on board the vessel.

VESSEL NAME: 407

DATES TESTS PERFORMED: PIPING 22 JUNE 21

SIX INCH HOSE 22 JUNE 21

SIX INCH HOSE 22 JUNE 21

GAUGES / AIR RECEIVER RELIEF VALVE 22 JUNE 21

FIXED PIPING: TESTED 22 JUNE 21, MAWP: 125 PSI TEST PSI: 200 PSI

(At least 1.5 times maximum allowable working pressure(MAWP). MAWP is the relief valve setting.)

PRESSURE RELIEF VALVES: TESTED @ 125 P.S.I. ON 22 JUNE 21

HOSE 6"X75' SER #71887: TESTED 22 JUNE 21, MAWP: 125 PSI TEST PSI: 200 PSI, DIESEL

HOSE 6"X75' SER #71889: TESTED 22 JUNE 21, MAWP: 125 PSI TEST PSI: 200 PSI,


Test performed at: MIAMI, FL.

Test method: HYDRO TEST

Signature:

Name:

Title:



Amos Delancy
Tankerman Supervisor

Company address: 1020 Port Blvd.
Miami, Florida 33132
Telephone: (305) 579-5013