KIRBY INLAND MARINE

ANNUAL CARGO PIPING AND HOSE TEST REPORT

Reference: 33CFR 156.170

A copy of this report is to be retained on board the vessel.

Vessel Name: 401

DATES TEST PERFORMED : PIPING 05 JULY 2024 CARGO PRESSURE RELIEF VALVES 05 JULY 2024 CARGO PRESSURE GAUGES 05 JULY 2024 AIR RECEIVER 05 JULY 24

PORTABLE HOSE # 3: TESTED 05 JULY 24, MAWP :125 PSI TEST PSI 200 6" x 75 WILCOX #1151 GG MARINE MASTER DOCK HOSE SER. # 88613-3

PORTABLE HOSE # 4: TESTED 05 JULY 24, MAWP :125 PSI TEST PSI 200 6" x 75 WILCOX #1151 GG MARINE MASTER DOCK HOSE SER. # 82083-2

Test performed at:

Port of Miami, Florida

Test method:

Hydro Test

Signature:

AMOS DELANCY

Title:

MARINE COORDINATOR

Company addr

1020 Port Blvd.

Miami, Florida 33132

Telephone:

(305)579-5013