

# KIRBY INLAND MARINE

## ANNUAL CARGO PIPING AND HOSE TEST REPORT SUMMERY

Reference: 33CFR 156.170

A copy of this report is to be retained on board the vessel.

**VESSEL NAME: 406**

**DATES TESTS PERFORMED: PIPING 25 SEPT 24**

**SIX INCH HOSE 25 SEPT 24**

**SIX INCH HOSE 25 SEPT 24**

**CARGO PRESSURE RELIEF VALVE 25 SEPT 24**

**GAUGES 25 SEPT 24**

**AIR RECEIVER RELIEF VALVE TESTED 25 SEPT 24**

**FIXED PIPING: TESTED 25 SEPT 24 MAWP: 125 PSI TEST PSI: 200 PSI**

(At least 1.5 times maximum allowable working pressure(MAWP). MAWP is the relief valve setting.)

**CARGO PRESSURE RELIEF VALVES: TESTED @ 125 P.S.I. ON 25 SEPT 24**

**HOSE 6"X75' SER #88613-2: TESTED 25 SEPT 24, MAWP: 125 PSI TEST PSI: 200 PSI, DIESEL**

**HOSE 6"X75" SER # 88613-1: TESTED 25 SEPT 24, MAWP : 125 PSI TEST PSI: 200 PSI, OIL**


Test performed at: Port of Miami - Miami,FI

Test method: HYDRO TEST

Signature:

Name:

Title:



Amos J DeLancy  
Tankerman Supervisor

Company address: 1020 Port Blvd.  
Miami, Florida 33132

Telephone: (305) 579-5013