

KIRBY INLAND MARINE, LP MAINTENANCE DEPARTMENT 18350 MARKET ST. CHANNELVIEW, TX 77530

OFFICE (713) 435-1730

FAX (713) 435-1714

VAPOR TIGHTNESS TEST

Note: Test Results a	re Valid for (1) One Y	ear from Da	ite of Test!	
/essel Name: HTCO 3080		Test Date:		4-27-202
	esting Location: Southwest Clean's		oad Rate: (B	and the second s
Tanks Tested:	ALL	Pressure Indicator:		Cert. Gaye
TEST RESULTS				
Test Duration: 30 Minutes Beginning Pressur		ıre:	28	Inches H20
Ending Pressure:			28	Inches H20
Total Pressure Los		oss:	Ø	Inches H20
	Allowable Pressu	re Loss:	2.29	_ Inches H20
Barge is Vapor Tight This vessel has been tes (/a/4 Moo/C Tester: (Print) Tester: (Signature)	if "Total Pressure Los ted in accordance with Se	Witness	and has been f	Montes
		Affiliation	Kins on of Witness	3:
(P1) - Beginning (Delta P) - Total Pres (TP) - 14.7 plus (V) - Volume of .861 - PIA @ (P1	sure Loss Barge Test Pressure in Tank (s)	PSI (L)	PM) - Allo	ling Pressure wable Pressure Loss timum Load Rate in BPH ration
.861 x	x(500 6	1 20	(V)) =