

## KIRBY INLAND MARINE, LP MAINTENANCE DEPARTMENT 18350 MARKET ST. CHANNELVIEW, TX 77530

OFFICE (713) 435-1730

FAX (713) 435-1714

## **VAPOR TIGHTNESS TEST**

Note: Test Results are V	alid for (1) One Year f	from Date of T	est!	
Vessel Name:	TCO 3104 Tes	t Date:		11/7/24
Testing Location:	275 Fleet Max	kimum Load Ra	te: (BPH)	0000
Tanks Tested:		ssure Indicator:		Cert Gaug
	TEST RE	SULTS		
Test Duration: 30 Minutes	Beginning Pressure:	78	3 Inche	es H20
	Ending Pressure:	21	3Inche	es H20
	Total Pressure Loss:	0	Inche	es H20
	Allowable Pressure Lo	oss: 2.3	Inche	es H20
Barge is Vapor Tight if "T This vessel has been tested in Daylon La G Tester: (Print)  Tester: (Signature)	n accordance with Section	LESS than "A 61.304F and has Witness: (Pr Witness: (Si Affiliation of the	s been found to be short with the short was gnature)	e vapor tight.
(P1) - Beginning Pre (Delta P) - Total Pressure (TP) - 14.7 plus Barg (V) - Volume of Tar .861 - PIA @ (P1)	e Loss ge Test Pressure in PSI			Pressure Loss Load Rate in BPH
.861 x	x( 5000 (L)	1 29(V	)=(	(Delta PM)