

KIRBY INLAND MARINE, LP MAINTENANCE DEPARTMENT 18350 MARKET ST. CHANNELVIEW, TX 77530

OFFICE (713) 435-1730

FAX (713) 435-1714

VAPOR TIGHTNESS TEST

Vessel Name:	16410059	Test Date:		12/	6/24	
Testing Location: 77. 237		Maximum Load Rate: (BPH) 3500				
Tanks Tested: All		_ Pressure Indicator:		Cert.	Cert Garge	
	TEST	T RESULTS			•	
Test Duration: 30 Minutes	s Beginning Pressu	ıre:	28	Inches H2	0	
	Ending Pressure:		28	Inches H2	0	
	Total Pressure Lo	oss:	<u>Ø</u>	Inches H2	0	
	Allowable Pressu	re Loss:	4.6	Inches H2	0	
This vessel has been tested	in accordance with Se	Ction 61.304F	and has bee	en found to be vap	or tight.	
Over On	ene	Witnes	(Print) s: (Print) s: (Signal on of With	7 Ross		
Tester: (Print) Tester: (Signature) P1) - Beginning Prince	essure	Witnes	S: (Signation of With	7 Ross		
Testery (Signature)		Witnes Affiliation (P2)	S: (Signal	g ess:		
P1) - Beginning Property Poelta P) - Total Pressur TP) - 14.7 plus Ba		Affiliation (P2)	S: (Signal on of With	ess:	ure Loss	
P1) - Beginning Property Poelta P) - Total Pressur	re Loss rge Test Pressure in	Affiliation (P2) (Delta PSI (L)	S: (Signal on of With	ess: Ending Pressure Allowable Pressure Maximum Load F	ure Loss	

WHITE COPY - VESSEL YELLOW COPY - BARGE DOCUMENT CONTROL COORDINATOR PINK COPY - BOOK COPY

Kirby Form #MR-06-02 Issued: 11/07/16