

KIRBY INLAND MARINE, LP MAINTENANCE DEPARTMENT 18350 MARKET ST. CHANNELVIEW, TX 77530

OFFICE (713) 435-1730

FAX (713) 435-1714

VAPOR TIGHTNESS TEST

Note: Test Results are Vessel Name: Testing Location: Tanks Tested:	//: /		5-	23-24 500
TEST RESULTS				
Test Duration: 30 Minutes		28	// Inches H	20
	Ending Pressure:	28	Inches F	120
	Total Pressure Loss:	0	Inches H	120
	Allowable Pressure Lo	ess: 4.26	Inches H	120
Barge is Vapor Tight if "Total Pressure Loss" is LESS than "Allowable Pressure Loss" This vessel has been tested in accordance with Section 61.304F and has been found to be vapor tight. Jaul Davis Witness: (Print)				
Tester: (Signature) Taul Dawn Witness: (Signature)				
Tester: (Signature) Witness: (Signature)				
		Affiliation of Witness:		
(V) - Volume of T .861 - PIA @ (P1)	ire Loss arge Test Pressure in PSI ank (s)		- Maximum Loa Fest Duration	ssure Loss d Rate in BPH
.861 x /5.7	×(<u></u>	1 1109)=	(Delta PM)
(17)	(L)	(•)		(20)