

## KIRBY INLAND MARINE, LP MAINTENANCE DEPARTMENT 18350 MARKET ST. CHANNELVIEW, TX 77530

OFFICE (713) 435-1730

FAX (713) 435-1714

	VAPOR TIG	HTNESS "	TEST	
Note: Test Results are	Valid for (1) One Ye	ar from Dati	e of Testl	
Vessel Name: KIN	184 10230	Test Date;		10-30-24
Testing Location: TT 104, 22C N		viaximum Load Rate: (BPH) 3, 500		
Tanks Tested:	A 22 F	ressure Indi	cator:	MANOMETER
TEST RESULTS				
Test Duration: 30 Minutes Beginning P		3); ************************************	28	Inches H20
	Ending Pressure:	P	28	Inches H20
	Total Pressure Loss	s:	0	Inches H20
	Allowable Pressure	Loss;	4.5	Inches H20
Barge is Vapor Tight if " This vessel has been tested  Shane Gui Tester: (Print)  Shame Su Tester: (Signature)	olny	Witness:	d has been found that the second that the seco	nd to be vapor light,
,		Affiliation	of Witness:	
(P1) - Beginning Pre (Delta P) - Total Pressure (TP) - 14.7 <u>plus</u> Barg (V) - Volume of Tan .861 - PIA @ (P1)	) Loss Je Test Pressure in PS	SI (L)	PM) - Allowe	g Pressure able Pressure Loss num Load Rate In BPH tion
.861 × /5.7 (TP)	X( <u>3,500</u> (L)	1. 10,	300 (V)	) = <u> </u>
			Trad to the contract of the co	** DE-A-May 24