

## KIRBY INLAND MARINE, LP MAINTENANCE DEPARTMENT 18350 MARKET ST. CHANNELVIEW, TX 77530

OFFICE (713) 435-1730

FAX (713) 435-1714

## **VAPOR TIGHTNESS TEST**

Note: Test Results are Valid for (1) One Year from Date of Test!			
Vessel Name: KIRBY ID447		est Date:	13 MAY 2025
Testing Location: SIENNA SHIPYARD		aximum Load Rate: (BP	H) 3500
Tanks Tested: ALL		ressure Indicator:	CERTIFIED GAUGE
TEST RESULTS			
Test Duration: 30 Minutes	Beginning Pressure:	28	_ Inches H20
	Ending Pressure:	28	_ Inches H20
	Total Pressure Loss	. <u>Z</u>	_ Inches H20
	Allowable Pressure	Loss: 4.7	_ Inches H20
Barge is Vapor Tight if "Total Pressure Loss" is LESS than "Allowable Pressure Loss".  This vessel has been tested in accordance with Section 61.304F and has been found to be vapor tight.			
WILLARD SWOKDS		Witness: (Print)	
Tester: (Print) Witness: (Print)			
Tester: (Signature) Witness: (Signature)			
		KIRBY INLAND MARINE	
		Affiliation of Witness	:
(P1) - Beginning Pressure		(P2) - End	ling Pressure
(Delta P) - Total Pressure Loss		(Delta PM) - Allo	wable Pressure Loss
(TP) - 14.7 plus Barge Test Pressure in PSI (L) - Maximum Load Rate in BPH			
(V) - Volume of Tank (s) (Delta T) = Test Duration			
.861 - PIA @ (P1)			
.861 x \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	_ x ( _ <u>3500</u> (L)	/ <u>IDDDD</u> (V)	) = <u>4.7</u> (Delta PM)