

## KIRBY INLAND MARINE, LP MAINTENANCE DEPARTMENT 18350 MARKET ST. CHANNELVIEW, TX 77530

OFFICE (713) 435-1730

FAX (713) 435-1714

## BARGE PIPING TEST LETTER

BARGE	NAME/NUMBER: Kirby	11344
Last Hydro Test Date (1.5 times)		
Note:	Test Results are Valid for (1) One Year from	Date of Test!
Letter	of Expiration Date (One year from Test):	11/15/25
The state of the s	Cargo Piping and Valves (Date of Test):	
	Annual Hydro Test Pressure:	125#
	Cargo Relief Valve Lift Test (Date of Test):	11/15/24
	Cargo Pressure Gauge (Date of Test):	11/15/24
ŭ.	Annual Percent of Accuracy (%):	98%
4	Steam Piping Test Pressure:	N/A
	Steam Relief Valve (Date of Test):	· N/A
	Signature: Oa. 7	

WHITE COPY - VESSEL YELLOW COPY - BARGE DOCUMENT CONTROL COORDINATOR

KIRBY FORM MR-05-03 ISSUED 07/10/18

PINK COPY - BOOK COPY