

## KIRBY INLAND MARINE, LP MAINTENANCE DEPARTMENT 18350 MARKET ST. CHANNELVIEW, TX 77530

OFFICE (713) 435-1730

FAX (713) 435-1714

## **VAPOR TIGHTNESS TEST**

Note: Test Results are V	alid for (1) One Year f	rom Date of Te	st!		
Vessel Name: <u>K</u> い	Name: <u>Ki/by [/5/3</u> Test		10-	-19-2024	
Testing Location:	g Location: TT/83 Max		ximum Load Rate: (BPH)		
nks Tested: A / / Pre		ssure Indicator:	_Ce,	rt grange	
TEST RESULTS					
Test Duration: 30 Minutes		28	Inches	H20	
	Ending Pressure:	28	Inches	H20	
Total Pressure Loss:			Inches	H20	
	Allowable Pressure Lo	ss: <u>4,2</u>	Inches	H20	
Barge is Vapor Tight if "Tester: (Print) Tester: (Signature)			been found to be  Ogas  it)  nature  183		
(P1) - Beginning Pres (Delta P) - Total Pressure (TP) - 14.7 <u>plus</u> Barg (V) - Volume of Tan .861 - PIA @ (P1)	Loss ge Test Pressure in PSI	(P2) (Delta PM) (L) (Delta T) = T	- Ending Press - Allowable Pr - Maximum Lo est Duration		
.861 x /5-7 (TP)	×( <u>3500</u> (L)	1 11040 (V)	)=)=	U.2 (Delta PM)	