

## KIRBY INLAND MARINE, LP MAINTENANCE DEPARTMENT 18350 MARKET ST. CHANNELVIEW, TX 77530

OFFICE (713) 435-1730

document mailbox.

FAX (713) 435-1714

## **BARGE PIPING TEST LETTER**

Last Hydro Test Date (1.5 times) 4-23-2023 (USCG Required at COI Inspection and USCG Periodic)  Note: Test Results are Valid for (1) One Year from Date of Test!  Letter of Expiration Date (One year from Test): 2-20-2025  1. Cargo Piping and Valves (Date of Test): 2-20-2024  Annual Hydro Test Pressure: 100 ps;  2. Cargo Relief Valve Lift Test (Date of Test): 5-10-2023  3. Cargo Pressure Gauge (Date of Test): 2-20-2024  Annual Percent of Accuracy (%): 99 %  4. Steam Piping Test Pressure: N/A  5. Steam Relief Valve (Date of Test): N/A	INSTRUCTIONS: FILL OUT COMPLETELY. WRITE "N/A" ON ANY NON-APPLICABLE LINE.
(USCG Required at COI Inspection and USCG Periodic)  Note: Test Results are Valid for (1) One Year from Date of Test!  Letter of Expiration Date (One year from Test): 2 · 20 · 2025  1. Cargo Piping and Valves (Date of Test): 2 · 20 · 2024  Annual Hydro Test Pressure: 100 ps.  2. Cargo Relief Valve Lift Test (Date of Test): 5 · 10 · 2023  3. Cargo Pressure Gauge (Date of Test): 2 · 20 · 2024  Annual Percent of Accuracy (%): 99 %  4. Steam Piping Test Pressure: N/A  5. Steam Relief Valve (Date of Test): N/A	BARGE NAME/NUMBER: Kirby 21852
1. Cargo Piping and Valves (Date of Test): 2 - 20 - 2025  1. Cargo Piping and Valves (Date of Test): 2 - 20 - 2024  Annual Hydro Test Pressure: 100 ps;  2. Cargo Relief Valve Lift Test (Date of Test): 5 - 10 - 2023  3. Cargo Pressure Gauge (Date of Test): 2 - 20 - 2024  Annual Percent of Accuracy (%): 99 %  4. Steam Piping Test Pressure: N/A  5. Steam Relief Valve (Date of Test): N/A	
Annual Hydro Test Pressure: 100 psi  2. Cargo Relief Valve Lift Test (Date of Test): 5 · 10 · 2023  3. Cargo Pressure Gauge (Date of Test): 2 · 20 · 2024  Annual Percent of Accuracy (%): 99 %  4. Steam Piping Test Pressure: N/A  5. Steam Relief Valve (Date of Test): N/A	
<ol> <li>Cargo Relief Valve Lift Test (Date of Test): 5 · 10 · 20 · 3</li> <li>Cargo Pressure Gauge (Date of Test): 2 · 20 · 20 · 20 · 20 · 20 · 20 · 20 ·</li></ol>	그는 그들이 얼마나 있다면 하는 아이를 하는데 하는데 됐다면 하다고 있다면 되었다. 그렇게 얼마나 얼마나 얼마나 얼마나 되었다면 하는데 그렇다.
Annual Percent of Accuracy (%): 99%  4. Steam Piping Test Pressure: N/A  5. Steam Relief Valve (Date of Test): N/A	2. Cargo Relief Valve Lift Test (Date of Test): 5 · 10 · 2023
5. Steam Relief Valve (Date of Test): NA	Annual Percent of Accuracy (%): 99 %
Signature:	Signature: Times of Tummersum

WHITE COPY - VESSEL YELLOW COPY - BARGE DOCUMENT CONTROL COORDINATOR PINK COPY - BOOK COPY

KIRBY FORM MR-05-03 ISSUED 07/10/18