



- |     |                         |     |                       |
|-----|-------------------------|-----|-----------------------|
| NO  | DESCRIPTION             | NO  | DESCRIPTION           |
| 1C  | CARGO TANK HIGH SUCTION | 9C  | CHECK VALVE           |
| 1Ca | CARGO TANK LOW SUCTION  | 11C | BLEED OFF VALVE       |
| 2C  | LOAD VALVE              | 19C | CARGO HEADER          |
| 3C  | MASTER SUCTION VALVE    | 30C | CARGO PIPELINE        |
| 4C  | DISCHARGE VALVE         | 36C | PRESSURE GAUGE        |
| 5C  | HEADER VALVE            | 37C | CARGO DROP            |
| 6C  | SALVAGE VALVE           | —   | — ABOVE DECK PIPING   |
| 8C  | RELIEF VALVE            | --- | --- BELOW DECK PIPING |

NOTE 1: CONTAINMENT P/S

TRINITY MARINE

REV.	DATE	BY	CHK	APP	REVISION DESCRIPTION
3	12/03/18	MRV	DDA	OF	ADDED HOT OIL DIAGRAM
2	11/11/09	RB	RB	OF	+ HIGH & LOW SUCTION
1	11/10/09	RB	RB	OF	DELETE CHK & BALL VLV.
0	06/29/09	RB	FP	OF	APPROVED



**KIRBY INLAND MARINE**

**CARGO**

**PIPING FLOW DIAGRAM**

**KIRBY 27712**

SCALE: NONE	REV. <b>3</b>
PAGE: 1 OF 2	

