

KIRBY INLAND MARINE, LP MAINTENANCE DEPARTMENT 18350 MARKET ST. CHANNELVIEW, TX 77530

OFFICE (713) 435-1730

FAX (713) 435-1714

VAPOR TIGHTNESS TEST

Note: Test Results are Valid for (1) One Year from Date of Test!				
Vessel Name: Kirby 27754		Test Date:		-29-24
Testing Location: Devils Elbow		Maximum Load Rate: (BPH) 5000		
Tanks Tested: ALL		Pressure Indicator:		- Gayge
TEST RESULTS				
Test Duration: 30 Minutes	Beginning Pressure:	28	Inches	H20
	Ending Pressure:	28	Inches	H20
	Total Pressure Loss:		Inches	H20
	Allowable Pressure Lo	oss: <u>2.4</u>	Inches H20	
Tester: (Signature) Barge is Vapor Tight if "Total Pressure Loss" is LESS than "Allowable Pressure Loss" This vessel has been tested in accordance with Section 61.304F and has been found to be vapor tight. Freddie David Witness: (Print) Witness: (Signature) Kirby Inland Marine Affiliation of Witness:				
(P1) - Beginning Pres		(P2)	- Ending Press	sure
(Delta P) - Total Pressure		(Delta PM)	- Allowable Pro	essure Loss
	ge Test Pressure in PSI	(L)	- Maximum Lo	ad Rate in BPH
(V) - Volume of Tank (s) (Delta T) = Test Duration .861 - PIA @ (P1)				
.861 x	x(<u>5000</u> (L)	127800 (V))=	2,42 (Delta PM)

WHITE COPY - VESSEL YELLOW COPY - BARGE DOCUMENT CONTROL COORDINATOR PINK COPY - BOOK COPY

Kirby Form #MR-06-02 Issued: 11/07/16