

KIRBY INLAND MARINE, LP MAINTENANCE DEPARTMENT 18350 MARKET ST. CHANNELVIEW, TX 77530

OFFICE (713) 435-1730

FAX (713) 435-1714

VAPOR TIGHTNESS TEST

Note: Test R	Results are V	alid for (1) On	e Year fron	Date of Te	st!	
Vessel Name:		28033				03/08/24
Testing Locati		Port Arthur			e: (BPH)	
Tanks Tested				e Indicator:		Cert Gauge
		TE	ST RESU	_TS		. /
Test Duration	: 30 Minutes	Beginning Pre	essure:	28		nches H20
		Ending Pressi	ure:	28		nches H20
		Total Pressure	e Loss:	0	1	nches H20
		Allowable Pre	ssure Loss:	2.13		nches H20
This vessel has	s been tested in	accordance with	Section 61.3	04F and has b	peen found	Pressure Loss" It to be vapor tight. Rodrigue
Tester. (Sig	fature)	\$		tness: (Sign	nature)	
, , , , , , , , , , , , , , , , , , , ,	,			LS		
				iliation of Wi	itness:	
(Delta P) -	elta P) - Total Pressure Loss			(P2) - Ending Pressure (Delta PM) - Allowable Pressure Loss (L) - Maximum Load Rate in BPH		
* *	Volume of Tar PIA @ (P1)			(Delta T) = Te		
.861 x	15.7 (TP)	x(_500) / (N)	3166 (V)	0)	= <u>2./3</u> (Delta PM)