

KIRBY INLAND MARINE, LP MAINTENANCE DEPARTMENT 18350 MARKET ST. CHANNELVIEW, TX 77530

OFFICE (713) 435-1730

FAX (713) 435-1714

VAPOR TIGHTNESS TEST

Note: Test Results are V			
Vessel Name: KINBY 2805 / Test Date: Testing Location: Southwest Cleaning. Partiant Load Rate: (BPH) Tanks Tested: ALC Pressure Indicator:			4-14-2024
Testing Location: Souther	est Cleaning. Mantaxim	num Load Rate: (BPI	H) 5,000
Tanks Tested:	ALC Press	ure Indicator:	Cert. Gauge
	TEST RESU	JLTS	
Test Duration: 30 Minutes	Beginning Pressure:	56	_ Inches H20
	Ending Pressure:	56	_ Inches H20
	Total Pressure Loss:		_ Inches H20
	Allowable Pressure Loss	2,50	Inches H20
Tester: (Signature)		Witness: (Print) Witness: (Signature Kings) Affiliation of Witness	Pontes Part re)
P1) - Beginning Pressure Delta P) - Total Pressure Loss TP) - 14.7 plus Barge Test Pressure in PSI V) - Volume of Tank (s) PIA @ (P1)		(Delta PM) - A	nding Pressure llowable Pressure Loss Maximum Load Rate in BPH Duration
.861 x	x(5000 (L)	1 28717 (V))= 2,50 (Delta PM)