

KIRBY INLAND MARINE, LP MAINTENANCE DEPARTMENT 18350 MARKET ST. CHANNELVIEW, TX 77530

OFFICE (713) 435-1730

FAX (713) 435-1714

VAPOR TIGHTNESS TEST

Vessel Name:	KIRBY 28061	Year from Date of Test! Test Date:	17 OCTOBER 2024
Testing Location:	GRALLING ANUSIS	Maximum Load Rate: (BPH)	5000
Tanks Tested:	ALL	Pressure Indicator:	CIRTIFIED GALGE
	TES	ST RESULTS	
Test Duration: 30 M	Minutes Beginning Pres	sure: <u>Fla</u>	Inches H20
	Ending Pressur	e: <u>56</u>	Inches H20
	Total Pressure	Loss:	Inches H20
	Allowable Press	sure Loss: 1 ,5 1	Inches H20
Tester: (Print)	Look	BILL AKERS Witness: (Print)	A. 2
Tester: (Signatur	ne)	Witness: (Signature)	
		Affiliation of Witness:	UNZ
(P1) - Begins	ning Pressure	(P2) - Endir	ng Pressure
(Delta P) - Total I	Pressure Loss	(Delta PM) - Allow	able Pressure Loss
(TP) - 14.7 g	lus Barge Test Pressure	in PSI (L) - Maxi	mum Load Rate in BPH
.861 - PIA @	e of Tank (s) (P1)	(Delta T) = Test Dur	ation
.861 x(TF	x (<u>5000</u>) × (<u>L)</u>	/ <u>28484</u> (V)	_) = <u>2.52</u> (Delta PM)