

## KIRBY INLAND MARINE, LP MAINTENANCE DEPARTMENT 18350 MARKET ST. CHANNELVIEW, TX 77530

OFFICE (713) 435-1730

FAX (713) 435-1714

## **VAPOR TIGHTNESS TEST**

Note: Test Results are Valid for (1) One Year from Date of Test!				
Vessel Name: YIL	29071 Tes	t Date:	<u>_</u>	13.24
Testing Location: ( ) ho	1 29071 Tes	timum Load Rate	e: (BPH) _5,0	00
Tanks Tested: AII	Pre	ssure Indicator:	Cevt	- Gauge
TEST RESULTS				
Test Duration: 30 Minutes	Beginning Pressure:	14	Inches I	120
	Ending Pressure:	14	Inches I	H20
	Total Pressure Loss:	0	Inches	H20
	Allowable Pressure Lo	oss: <u> </u>	3Inches	H20
Barge is Vapor Tight if "Total Pressure Loss" is LESS than "Allowable Pressure Loss" This vessel has been tested in accordance with Section 61.304F and has been found to be vapor tight.				
Tester: (Print) Witness: (Print)				
122				
Tester: (Signature)  Witness: (Signature)				
Striky tarts				
	Affiliation of Witness:			
(P1) - Beginning Pres	ssure	(P2)	- Ending Press	ure
(Delta P) - Total Pressure Loss		(Delta PM)	- Allowable Pre	ssure Loss
(TP) - 14.7 plus Barge Test Pressure in PSI		(L)	- Maximum Load Rate in BPH	
(V) - Volume of Tank (s) (Delta T) = Test Duration				
.861 - PIA @ (P1)				
.861 x	x( <u>5,000</u> (L)	1 29,7°(V)	)=	(Delta PM)