

KIRBY INLAND MARINE, LP MAINTENANCE DEPARTMENT 18350 MARKET ST. **CHANNELVIEW, TX 77530**

OFFICE (713) 435-1730

FAX (713) 435-1714

VAPOR TIGHTNESS TEST

Note: Test Resu Vessel Name: Testing Location: Tanks Tested:	Kirb	Lemont IL	Test Da	ate:	e: (BPH)	6-5-24 5000 Cert Cause
TEST RESULTS						
Barge is Vapor Ti This vessel has bee XonButch Tester: (Print) Youk Tester: (Signatu	i ght if "T on tested in	Beginning Pressure: Ending Pressure: Total Pressure Lo Allowable Pressu otal Pressure Los accordance with Se	re Loss: s" is LE ction 61.3	2,3	Ilowable been fount) Int) Int) Int) Int) Int) Int) Int) I	lez L
(Delta P) - Total (TP) - 14.7 g	olus Barg ne of Tan (P1)	Loss e Test Pressure in	PSI	(P2) (Delta PM) (L) (Delta T) = 29 10 (V	- Allow - Maxii Test Dura	rable Pressure Loss mum Load Rate in BPH ation