


- |     |                            |     |                          |
|-----|----------------------------|-----|--------------------------|
| NO  | DESCRIPTION                | NO  | DESCRIPTION              |
| 7V  | 8" HEADER VALVE            | 30V | THERMAL WELL             |
| 8V  | 8" VENT STACK VALVE        | 38V | 8" VAPOR PENETRATION (⊙) |
| 10V | HIGH LEVEL/OVERFILL ALARM  | 39V | PRESSURE/VACUUM VALVE    |
| 11V | 1-METER GAUGE STICK        | 50V | 8" VAPOR HEADER          |
| 14V | SIGHT GLASS W/ GAUGE TREE  | 51V | 8" VAPOR PIPELINE        |
| 16V | VAPOR VENT STACK           | 59V | PRESS/VAC GAUGE          |
| 19V | EMERGENCY ENGINE SHUT DOWN | —   | ABOVE DECK PIPING        |
| 28V | DOCK CONNECTION ALARM      |     |                          |


NOTE 2: TYPICAL RIGGING IN EACH TANK  
 NOTE 1: CONTAINMENT P/S

						<b>KIRBY INLAND MARINE</b>	
1	06/08/24	AC	DDA	DAR	REVISED PER CLIENT COMMENTS	SCALE: NONE <b>MMI 3051</b>	
0	02/08/19	MRV	DDA		ISSUED FOR APPROVAL		
REV.	DATE	BY	CHK	APP	REVISION DESCRIPTION	PAGE: 2 OF 3	REV. <b>1</b>



- | NO  | DESCRIPTION          |
|-----|----------------------|
| 10H | SUPPLY VALVE         |
| 11H | RETURN               |
| 12H | PRESSURE REGULATOR   |
| 13H | BY-PASS              |
| 16H | ISOLATION VALVE      |
| 17H | BASKET STRAINER      |
| 18H | CHECK VALVE          |
| 19H | DRIP PAN DRAIN VALVE |
- ABOVE DECK PIPING

NOTE 1: 6 BARREL DRIP PAN

						<b>KIRBY INLAND MARINE</b> 	
1 06/08/24 AC DDA DAR REVISED PER CLIENT COMMENTS						SCALE: NONE	
0 02/08/19 MRV DDA ISSUED FOR APPROVAL						<b>MMI 3051</b>	
REV.	DATE	BY	CHK	APP	REVISION DESCRIPTION	PAGE: 3 of 3	
							<b>REV. 1</b>